Prince of Songkla University

Faculty of Engineering

Final Examination: Semester 1

Academic Year: 2006

Subject: 226 – 409 Machining Technology

Time: 9.00 - 12.00

Date: 7 October 2006

Room: A401

ทุจริตในการสอบ โทษขั้นต่ำคือปรับตกในรายวิชาที่ทุจริต และพักการเรียน 1 ภาคการศึกษา

- ห้ามใช้โทรศัพท์มือถือ หรือเครื่องมือสื่อสารในห้องสอบ
- อนุญาคให้นำกระคาษขนาด A4 บันทึกโน้คใดๆก็ได้ เข้าห้องสอบได้ไม่เกิน 1 แผ่น นำเครื่องกิดเลขรุ่นใดเข้าห้องสอบก็ได้ แต่ห้ามนำหนังสือ หรือ Sheet อื่น ๆ เข้าห้องสอบ

Answer all the questions in the book provided. There are 5 questions. The full marks are 50.

1. In machining of stainless steel work piece with a carbide tool, the tool life equation is $T = k \, v^{-0.5} \, f^{-4.0}$

When T = tool life (min), v = cutting speed (m/min), f = feed rate (mm/rev)

At present the cutting condition was v = 100 m/min, f = 0.1 mm/rev, T = 60 min.

If the manufacturer wants to use a new cutting condition with v=150 m/min, and f=0.05 mm/rev, what is the new value of tool life?


(10 Marks)

2. When a cutting tool "A" is used to cut a tool material "B" the value of v_{60} is 50 m/min. and v_{30} is 80 m/min. What is the value of v_{10} .

(10 Marks)




- 3. Answer the following questions.
- 3.1 Automated guided vehicles (AGV) are arranged into 1 simple loop as shown in the sketch. Explain 2 systems that can be used to prevent AGV from collision.



3.2 Write 3 reasons why a robot should be used to replace human. Give some examples in your explanation.

(10 Marks)

- 4. Answer the following questions.
- 4.1 CO₂ laser used one of the many modes of molecular vibration to generate the monochromatic light beam. If the CO₂ molecule can be represented by the following picture, use the picture to explain 3 different ways that vibration can take place.




4.2 In a He Ne laser, Ne is known to be the luminant that releases light energy. What is the role that He plays in the light emission process?

(10 Marks)

- 5. Answer the following questions.
- 5.1 In electric discharge machining, the workpiece is made a positive electric pole while the tool is made a negative pole. A dielectric liquid, ie. kerosene, is placed in the middle as shown in the sketch.

Explain why the dielectric liquid must be put in between the tool and the workpiece.



5.2 Water abrasive jet machining uses abrasive grains and high speed water jet to cut stones and marbles. Explain the roles of the abrasive grains and the water jet in machining.

(10 Marks)

+-+-+-+-+-+-+-

Assoc. Prof. Dr. Supachok Wiriyacosol

M