

PRINCE OF SONGKLA UNIVERSITY FACULTY OF ENGINEERING

Final Examination: Semester 1

Date: 15 OCT 9010

Time: 13 30-16:30

Academic Year: 2010

Subject: 225-349 Safety and Environmental Engineering Room: R200

คำสั่ง

- 1. ข้อสอบมีทั้งหมด 4 ส่วน ในกระดาษคำถาม 10.หน้า รวมหน้าปก (นับให้ครบก่อนลงมือ ทำ)
- 2. ห้ามการหยิบยืมสิ่งใด ๆ ทั้งสิ้น จากผู้อื่น ๆ เว้นแต่ผู้คุมสอบจะหยิบยืมให้
- 3. ห้ามน้ำส่วนใดส่วนหนึ่งของข้อสอบออกจากห้องสอบ
- 4. ผู้ที่ปฏิบัติเข้าข่ายทุจริตในการสอบ ตามประกาศคณะวิศวกรรมศาสตร์ <u>มีโทษ คือ ปรับตก</u> ในรายวิชาที่ทุจริต และพักการเรียน 1 ภาคการศึกษา
- 5. ให้ทำในกระดาษคำตอบเท่านั้น ตอบนอกกระดาษ คำตอบไม่มีคะแนน
- 6. เขียน ชื่อ **หรือรหัส** ในกระดาษคำตอบทุกหน้าก่อนเริ่มทำ เพื่อป้องกันความสับสน ในกรณี กระดาษคำตอบหลุดจากฉบับ
- 7. ให้นักศึกษาสามารถนำสิ่งต่อไปนี้เข้าห้องสอบได้

□ หนังสือ
☑ กระดาษ A4 เขียนด้วยลายมือตนเอง 3 แผ่น

"ส่งกระดาษ ${f A4}$ ทั้ง ${f 3}$ แผ่นมาพร้อมกระดาษคำตอบด้วย"

🗹 นำ Dictionary และ เครื่องคิดเลข เข้าห้องสอบได้

8. ให้ทำข้อสอบโดยใช้ 🔲 ดินสอ 🗹 ปากกา

Question#	1	2	3	4	5	Total
Full score	10	35	10	20	36	111
Score						

ผู้ออกข้อสอบ ผศ.ดร.กลางเดือน โพชนา

<u>Part 1</u> Answer all questions. Please determine whether these following sentences are correct or incorrect. One point (1 point) will be given for the right answer. Minus half point (-0.5 point) will be given for the wrong answer. (Total 10 points)

Q no. 1.	Correct	Incorrect	Question
	✓	*	
1			In case of electricity leakage, cement or earthen floor is more dangerous than dry wooden floor.
2			Temperature is one of the factors that increase the severity in electric shock.
3			The amount of smoke and toxic from welding process depends on welding method.
4			The certification body is the second party that is responsible for certifying ISO.
5			The method used for measuring the thickness of boiler wall is ultrasonic testing.
6			Static electricity can cause fire when it hits negative or positive object.
7			Radiation heat is a function of skin temperature and radiated temperature; it can be estimated by using globe thermometer.
8			Dry hot skin and very high body temperature is the sign of heat stroke.
9			Heat cramp is the most dangerous body abnormality caused by heat.
10			One of the advantages of sweep devices is easy to be adjusted.



Part 2. Select optimum answers. (35 points)

Part 2	. Select opt	ımum ansv	vers. (35 p	ooints)		
Q	Answer					
1	а	b	c	d		
2	а	b	С	d		
3	а	b	c	d		
4	а	b	c	d		
5	a	b	c	d		
6	а	b	С	d		
7	а	b	c	d		
8	а	b	с	d		
9	а	b	c	d		
10	a	b	c	d		
11	а	b	c	d		
12	а	b	с	d		
13	a	b	c	d		
14	а	b	c	d		
15	а	b	С	d		
16	а	b	c	d		
17	a	b	c	d		
18	a	b	c	d		
19	а	b	c	d		
20	a	b	c	d		
21	a	b	С	d		
22	a	b	С	d		
23	a	b	С	d		
24	a	b	с	d		
25	a	b	c	d		
26	a	b	с	d		
27	a	b	c	d		
28	a	b	с	d		
29	a	<u>ь</u>	c	d		
30	a	b	c	d		
31	a	<u>ь</u>	c	d		
32		b		d		
33	a	<u>в</u>	С С	d		
	<u>a</u>		c			
34	a	b	c	d		
35_	a	b	С	d		

- 1. In working area of 700 m², number of fire extinguisher should not be less than.....
 - a) 1
 - b) 3
 - c) 5
 - d) 7
- 2. According to Thai regulations, in normal condition of working area (8 hours/day) the noise should not be more than
 - a) 80 dBA
 - b) 90 dBA
 - c) 100 dBA
 - d) 110 dBA
- 3. Ear plug should be able to reduce noise at least.....
 - a) 10 dBA
 - b) 15 dBA
 - c) 20 dBA
 - d) 25 dBA
- 4. Ear muff should be able to reduce noise at least.....
 - a) 10 dBA
 - b) 15 dBA
 - c) 20 dBA
 - d) 25 dBA
- 5. ISO is from....
 - a) International standard organization
 - b) Interrelation organization standard
 - c) International organization for standardization
 - d) International organization in standard
- 6. Occupational Safety and Health Administration (OSHA) of USA recommends that worker should not completely work in workplace that has noise more than
 - a) 120 dBA

Student name and code:	(กรอกเฉพาะหน้าที่เป็นกระคาษคำตอบ)
b) 130 dBA	b) มอก. 14000
c) 140 dBA	c) มอก. 18000
d) 150 dBA	d) no correct answer
	d) no contest and wer
 7. The pressure of fire sprinkle should not be less than a) 8 psi b) 9 psi c) 10 psi d) 11 psi 	 13. According to safety laws, workplace area for each worker should not be less than a) 3 m² b) 4 m² c) 5 m²
	d) 6 m^2
 8. Portable fire extinguisher should be installedabove floor level. a) 0.8-1 m b) 1-1.4 m c) 1.2-1.5 m d) 1.3-1.6 m 	 14. Which answer is not an element of fire pyramid? a) Oxygen b) Temperature c) Chain reaction d) Wind
9. The temperature in workplace should	
not be more than	15. What type of fire is caused by electrical
a) 40 °C	problem?
b) 45 °C	a) A
c) 50 °C	b) B
d) 55 °C	c) C d) D
3, 33 3	u) D
 10. The light in walkway of warehouse should not be less than	 16. According to fire diamond, which color indicates level of flammability? a) Blue b) Red c) Yellow d) White
 11. According to Interior Acts, fire extinguishing practice should be conducted at least a) Once per year b) Once per quarter c) Every second month d) Twice per year 	 17. The internal audit required by the ISO is normally called a) first party audit b) second party audit c) third party audit d) forth party audit
12. What is the Industrial Standard used for Occupational Health and Safety?	18. Which detector is NOT used for fire accident detection and prevention?a) Frame Detectorb) Heat Detector

~4~

a) มอก. 9000

Sur

c) Fume Detectord) Smoke Detector

- 19. What is the cause of boiler explosion that normally found in Thailand?
 - a) water is dry
 - b) safety valve does not work
 - c) exceed of power supply
 - d) fire leakage from boiler
- 20. What is the width of factory pathway that is sufficient for two ways transportation with 4 wheels vehicle?
 - a) Two times of vehicle width.
 - b) Two times of vehicle width plus 20 inches.
 - c) Two times of vehicle width plus 36 inches.
 - d) Three times of vehicle width.
- 21. Which class of safety helmet is <u>not</u> suitable for electrical work?
 - a) Class A
 - b) Class B
 - c) Class C
 - d) Class D
- 22. In a factory, the forklift driver should not drive faster than
 - a) 15 km/hr
 - b) 20 km/hr
 - c) 25 km/hr
 - d) 30 km/hr
- 23. Which answer is correct?
 - a) Water tube boiler is normally cheaper than fire tube boiler
 - b) Water tube boiler normally produces steam faster than fire tube boiler
 - c) The external inspection of fire tube boiler is easier than water tube boiler
 - d) Fire tube boiler is more safe comparing with water tube boiler

24. Which picture is a correct method of using grip?

а	Offergentie
b	Offerfree
С	O Para Para Para
d	All answers are wrong

- 25. The external party that assesses the organization's ability to meet customer, statutory and regulatory requirements according to ISO standard. It is called.....
 - a) Non Government Organization
 - b) Certification Bodies
 - c) Accreditation Bodies
 - d) International Organization for standardization
- 26. What type of external audit is a routine assessment that required by ISO in order to monitor the ISO14001 conformation of the organization?
 - a) Surveillance audit
 - b) Certification audit
 - c) Pre-audit
 - d) Re-assessment audit
- 27. Which answer is correct?
 - a) "Form" is used for production but "record" is used for management
 - b) "Form" has specific pattern, but "record" has no pattern

Supr

- c) "Form" shows current status of document, but "record" shows current revision of document
- d) No correct answer
- 28. Which color should be used for machine guard?
 - a) red
 - b) yellow
 - c) blue
 - d) black
- 29. Which type of machine is not suitable for using two switches control machine guard?
 - a) Metal press brake machine
 - b) Drill machine
 - c) Metal power press machine
 - d) Die cutting machine
- 30. According to heat balance, which factor is not related?
 - a) Convection
 - b) Radiation
 - c) Evaporation
 - d) Conduction
- 31. How long is the certification of ISO14001?
 - a) 2 years
 - b) 3 years
 - c) 4 years
 - d) 5 years
- 32. What is the major cause of accident form machine?

- a) unsafe act
- b) unsafe condition
- c) unsafe machine
- d) unsafe environment
- 33. What is the attitude of most of the workers on machine guard?
 - a) easy to work with machine guard
 - b) using machine guard causes their work efficiency reduced.
 - c) machine guard is normally located in proper position
 - d) machine is necessary for their work safety
- 34. What is the suitable characteristic of water for water tube boiler?
 - a) total dissolved solid less than 4,000 ppm
 - b) pH 7-9
 - c) temperature not more than 80°C
 - d) total suspended solid less than 3,500 ppm
- 35. What is the indicator that indicates the danger from heat?
 - a) THS
 - b) TWAN
 - c) EWMA
 - d) HSI

Sir

Student name and code:(f	ารอกเฉพาะหน้าที่เป็นกระคาษคำตอบ
--------------------------	---------------------------------

Part 3: answer these following questions with detail calculation. (10 points)

1. In a feed mill factory, there are 3 machines (with SPL 99,95, and 100 dBA) located in the same room. Please calculate total dBA of this room. Show your calculation. (5 points)

2. In a furniture factory, a worker works near press machine with 90 dBA for 5 hour, lathe machine with 96 dBA for 0.5 hour and grinding machine with 96 dBA for 0.5 hour. Please calculate TWAN (Time-Weighted Average Noise). Show your calculation. (5 points)

Number of working hour (per day)	Sound level (dBA)
8	90
4	93
2	96
1	99
1/2	105
1/4	120

Som

	Student name and code :(กรอกเฉพาะหน้าที่เป็นกระคาษคำตอบ)
<u>Par</u>	t 4 : Fill in the blank. (20 points)
1.	is the process that reclaims the useful materials from the waste produced by the public. (2 points)
2.	The separation into different types of materials by the person who decides to produce the solid waste, the collection and subsequent reintroduction of this material into the public sector, is known as(2 points)
3.	Source separation is only the first step in the process that must include collection, processing, transport, and eventually sale to an industry that then uses the material. (2 points)
4.	In sanitary landfills, liners are used to try to prevent the movement of into the groundwater. (2 points)
5.	Sanitary landfills are not inert. The buried organic material decomposes anaerobically, producing various gases, such as
6. V	Which type of fire is the following: (Type A, B, C, or D) (1 point each)
Exa	mple:A Cloths
	6.1 NGV
	6.2 Fire involving paper
	6.3 Electric Switch
	6.3 Electric Switch 6.4 Benzene oil
	6.4 Benzene oil
	6.4 Benzene oil 6.5 Metallic fire such as magnesium
	6.4 Benzene oil 6.5 Metallic fire such as magnesium 6.6 Motor
	6.4 Benzene oil 6.5 Metallic fire such as magnesium 6.6 Motor 6.7 Biodiesel

Som

	. •	പ്പ്	
Student name and code:(ักรอกเฉพาะหน้า	ที่เป็นกระด	งาษคำตอบ

Part 5: Answer these following questions. (36 points)

กรณีศึกษา

สุชาติ เข้าทำงานเป็นวิศวกรในบริษัทผลิตเฟอร์นิเจอร์ไม้ยางพาราแห่งหนึ่ง ได้มีเหตุการณ์เกิดขึ้นตามลำดับดังนี้

	วันที่	เหตุการณ์	ตอบ
1	10 สิงหาคม	เกิดไฟไหม้ที่คลังเก็บอุปกรณ์ ซึ่งมีชั้นวางของต่างๆมากมาย	
		อยู่ในคลังคังกล่าว สาเหตุของการเกิดไฟไหม้มาจากมี	
		สารเคมีติดไฟลุกไหม้ขึ้น สุชาติทำหน้าที่ดับเพลิงในครั้งนั้น	·
		พร้อมค้วยทีมดับเพลิงของบริษัทอีก 2 คน เมื่อสุชาติพร้อม	
		ทีมคับเพลิง เข้าไปคับไฟตอนเกิดไฟไหม้ เขาควรจะใส่	
		หมวกนิรภัยประเภทใค และควรใส่ชุดป้องกันความร้อน	
		ประเภทใด เพราะอะไร	
2	15 กันยายน	เกิดการรั่วใหลของสารเคมีจากท่อส่งสารเคมีในห้อง	
		กระบวนการล้าง โดยในห้องคังกล่าวมีขนาดของห้อง	
		ประมาณ 4x10 ตร.ม. ในขณะเกิดเหตุสุชาติเป็นผู้รับผิดชอบ	
		ในการเข้าไปปีควาล์วของสารเคมีในห้องนั้น และทำหน้าที่	
		ซ่อมท่อสารเคมีที่รั่ว โดยต้องใช้เวลาในการซ่อมท่อ	
		คังกล่าวเป็นเวลา 2-3 ชั่วโมง ในขณะที่สุชาติเข้าไปช่อมท่อ	
		สารเคมีรั่ว สุชาติควรสวมใส่ อุปกรณ์ป้องกันการหายใจ	
		(Respiratory protection devices) ประเภทใด เพราะอะไร	
3	20 กันยายน	เกิดมีปัญหาเรื่องไฟฟ้าหลักของโรงงาน ดังนั้นทางทีม	
		วิศวกรจึงต้องซ่อมแซมระบบไฟฟ้า เมื่อสุชาติด้องเข้า	
		ปฏิบัติงานในการช่อมระบบไฟฟ้าในโรงงาน สุชาติควร	
		สวมหมวกนิรภัยประเภทใค (class) และถุงมือประเภทใค	
4	10 ตุลาคม	มีอุบัติเหตุเกิดกับคนงานแผนกเถื่อย ในการทำงานกับเครื่อง	
		เลื่อยวงเคือนคนงานใช้อุปกรณ์ช่วยป้อนชิ้นงานคันไม้ที่มี	
		ตาไม้เข้าหาใบเลื่อย เนื่องจากตาไม้แข็งมากเมื่อป้อนเข้าไป	
		จึงสะคุคกับฟันเลื่อยทำให้ไม้สะบัค มือของคนงานพลาคไป	
		สัมผัสถูกกับใบเลื่อยได้รับบาดเจ็บ ในฐานะที่สุชาติเป็น	
		วิสวกรควบคุมการผถิตของโรงงานแห่งนี้ ท่านคิดว่าสุชาติ	
		ควรจะคำเนินการป้องกันอย่างไร	
5	2	พนักงานใหม่เข้ามาทำงานแผนกอบไม้ โรงงานนี้มีการ	
	พฤศจิกายน	เคลื่อนย้ายวัสคุในโรงงานโดยใช้ปั้นจั่นเหนือศีรษะ	
		(Overhead Crane) ชนิคที่มีสวิทซ์ควบคุมที่พื้น สุชาติควร	
		จะแนะนำพนักงานงานใหม่ในการใช้อุปกรณ์ควบคุม	
		อย่างไร	

Sur

		รไชเง่อโปนตรายานใรเกสิดินรัพเกิกในรมเดิง
		ตัวแนะนำในการใช้อุปกรณ์ป้องกันทูแบบใด และมี
		แนะนำให้โรรงานจัดหาอุปกรณ์ป้องกันทู สุชาติจะให้
	บ์ทบาพูทมุ	ล้ไรอินนั้รคั อเกเมซิคเ 29 นกิเรยทีรยดเรลินกรศนีกน้ำอไ อนัก
12	07	พางกรมโรงงานเข้ามาตรวจเชียมโรงงาน พบว่าบริเวณใกล้
	ัชนพากนก ก	Expanstion) สุชาติจะมีวิธีการในการปฐมพยาบาลอย่างไร
11	14	มีพนักรานแผนกเตาอน หมดแรงเนื้องจากรือนจัด (Heat
		<i>ุ</i>
		บนของโต๊ะ เป็นค้น สุขาติมีคำแนะนำในการติดคั้งอุปกรณ์
		เก็บชิ้นส่วนระหว่างการผลิตเฟอร์นิเจอร์ เช่น ขาโต๊ะ หน้า
		นรัพาทัพนีที่พื้นที่พื้นที่พื้นที่พื้นที่พื้นที่ รดนายาราค 002 กลีนายรรไ
10	30 nullun :	ผู้บรางคือการขยายพื้นที่ของโรรงานออกไปคำหหลัง
		อะไร
		ใช้ในโรงงาน กุษาศิควรจะแนะนำกิจกรรมอะไรบ้าง เพราะ
6	ร ภมมามภ	หู้บราหารนินโขบางที่จะนี้กิจกรามส่งเสริมความปลอดกับมา
-		
		ะเนีรใจเนื้อนี้อนี้หรัพิคดิ์รเก
8	uarcut oi	นใกละนำเคือนี้กับเบบท่อน้ำ สุชาติจะมีคำแนะนำใน
 		
		ารแนะนำเพื่อลดอุบัติเหตุจากการใช้รถยกอย่างไรบ้าง
	พย่นอูมเถท	นใช้เนื่อจัดเชก แล้ว กลักเกรเทนเล่นข้อนี้มน่อหกดรอย น่นเ
L	30	มีหนักจานข้ารถยก (Fork lift) มีอุบัติเหตุอากการข้ารถยก
<u> </u>		slorio
ſ		เป็นลักษณะอาการผิคปรกติโค และควรปฐมพยาบาล

Good luck!!!

Asst. Prof. Dr. Klangduen Pochana.

