มหาวิทยาลัยสงขลานครินทร์ คณะวิศวกรรมศาสตร์

การสอบปลายภาค ประจำภาคการศึกษาที่ 1 วันที่ 29 ักรกฎาคม 2556 วิชา 211-232 Sensor & Signal Conditioning ปีการศึกษา 2556 เวลา 9:00-12:00

ห้อง A 4 0 O

คำสั่ง - ห้ามนำเอกสารใดๆเข้าห้องสอบ

- ให้นำเครื่องคิดเลขเข้าห้องสอบได้
- ข้อสอบมีทั้งหมด 7 ข้อให้ทำทุกข้อ
- ข้อสอบมี 8 หน้ารวมปก

ชื่อ			
รหัส			

1. Explain an example for an application of measuring instruments.

- 2. Explain what is meant by:(a) active instruments

 - (b) passive instruments.

Give examples of each and discuss the relative merits of these two classes of instruments.

3. A force sensor measures a range of 0 to 150 N with resolution of 0.1% FS. Find the smallest change in force that can be measured.

4. Explain the difference between accuracy and precision in an instrument.

5. A load cell is calibrated in an environment at a temperature of 21°C and has the following deflection/load characteristic:

CF					
Load (kg)	0	50	100	150	200
Deflection (mm)	0.0	1.0	2.0	3.0	4.0

When used in an environment at 35°C, its characteristic changes to the following:

Load (kg)	0	50	100	150	200
Deflection (mm)	0.2	1.3	2.4	3.5	4.6

- (a) Determine the sensitivity at 21°C and 35°C.
- (b) Calculate the total zero drift and sensitivity drift at 35°C.
- (c) Hence determine the zero drift and sensitivity drift coefficients (in units of μm /°C and (μm per kg)/(°C)).

6. A 350° pot is connected through a 4:1 gear ratio to a shaft that rotates 80° (the pot rotates four times further than the shaft). The pot has a supply voltage of 5 V and feeds to an 8-bit ADC converter. The ADC has a reference voltage of 5 V. The LSB of the ADC is to be 0.4° or smaller. Will this system meet the requirements?

7. Construct a force sensor with the following characteristics;

Range: 0-30 lb
Deformation: 0.5 in. (maximum)
Output: 0.1 V/lb

A 1 $k\Omega$ linear motion pot is available with a 1-in. stroke.